



Argyll & Bute Council as SHA received notification from KHM CLYDE that the leading lights on approach to Campbeltown Loch are to be switched off and isolated.

³ «as the owners of third-party navigation aids within your Harbour Authority, we will be isolating the power to the leading lights which are under our ownership. This is due to the current electrical condition and material state of the infrastructure. This measure is necessary to ensure the safety and integrity of the system. The leading lights will be off for a prolonged period to allow for all the required remedial works to be carried out. We understand the importance of these navigation aids and are committed to bringing them back into service as swiftly as possible. »

Mariners are therefore requested to manoeuvre and transit Campbeltown Loch with extreme caution especially during the period from dusk until dawn, and in cases of restricted visibility.




FIG: RED AREA DENOTES POSITION OF LEADING LIGHTS AND BEARING

Further 9.27 2((r)-3(4.25 Tag 0 G 1 0 0 16Bt)-o0 0 5 Tagm 0 1 qo0n275 0 g 527 2(

Harbour Office, Ferry Terminal Building, New Quay, Campbeltown, Argyll, PA28 6BA
Tel: 01586 552552 Email: campbeltownharbour@argyll-bute.gov.uk