

**DALINTOBER PRIMARY SCHOOL**

---

**1.0 EXECUTIVE SUMMARY**

- 1.1 This report sets out the current position in respect of Dalintober Primary School, in response to concerns that have been raised in respect of the condition and safety of the building.
- 1.2 Members are asked to:-
- 1.2.1 Note the contents of the report; and
  - 1.2.2 Agree that the condition survey, currently scheduled for 2021/22, is brought forward to this year.

**DALINTOBER PRIMARY SCHOOL**

---

**2.0 INTRODUCTION**

- 2.1 This report sets out the current position in respect of Dalintober Primary School, in response to concerns that have been raised in respect of the condition and safety of the building.

**3.0 RECOMMENDATIONS**

Members are asked to:-

- 3.1 Note the contents of the report; and
- 3.2 Agree that the condition survey, currently scheduled for 2021/22, is brought forward to this year.

**4.0 DETAIL**

- 4.1 Dalintober Primary School is situated in the former royal burgh of Campbeltown. The oldest part of the building was built in 1889. Dalintober currently has a primary school roll of 255 and provides Ety sttha

timely communications to parents/carers, ensured that this was a smooth process for all involved. The second incident at the end of February 2020 was not related to the initial incident or any repair works undertaken. Immediate action was taken by Property Services to make safe and arrange the necessary repair. There was no pupil displacement required due to the second incident.

4.4 Since 30<sup>th</sup> January<sup>†</sup>

identified. Any issues which may arise from the structural survey will be dealt with in terms of the Council's capital expenditure processes.

## **5.0 CONCLUSION**

5.1 Following recent property issues at Dalintober Primary School, this report sets out details of the remedial works and measures that have been put in place to ensure the continued safety of pupils and staff within the building.

## **6.0 IMPLICATIONS**

6.1 Policy – none at this time

6.2 Financial – none at this time

6.3 Legal – none at this time

6.4 HR – none at this time

6.5 Fairer Scotland Duty: none

6.5.1 Equalities - protected characteristics - none

6.5.2 Socio-economic Duty - none

6.5.3 Islands - none

6.6. Risk - appropriate measures put in place to ensure the learning and teaching environment remains safe

6.7 Customer Service – none

**Douglas Hendry**  
**Executive Director with responsibility for Education**

**Policy Lead – Councillor Yvonne Mcneilly**

3 March 2020

**For further information contact:**

Laura Blackwood  
Directorate Support Officer  
Customer Services  
01546 604325